

TO BE FILLED BY THE INSPECTING OFFICER
(Assistant Engineer / Assistant Executive Engineer)

Name of School Marka2 Public School Balussery

1. Name of the Officer LIJINA.M

2. Location Balussery

3. Period for which the certificate is issued 2023-24

4. Types of building RCC bldg (Permenant)

5. Nature of defect if any
Class Room } 3x44.0 5x9.20 x 3.70
GF, FF, }
& SF } 3x16.20 x 9.20 x 3.70

a) Foundation and basement

b) Superstructure

c) Doors and windows

NILL

d) Wood work wrought and put up

e) Roof

f) Flooring

g) Miscellaneous (Cracks if any)

6. Any major defects noticed which will render the building unsafe in any manner NO

7. Whether maintenance work have been done properly Yes

8. Whether the structure is sound or not for conducting classes. The Structure is sound for conducting classes at Normal wind & weather condition


Note : 1 The Stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.

2 Any additional observation deemed necessary for the Certificate, may be furnished separately with the Certificate.

Certified that the School was inspected by me on 25/08/2023 and found to be, fit / unfit to conduct classes for the period / for the reasons stated above.

Place : Balussery

Date : 25/08/23.



Signature

Designation

LiJina.M
ASSISTANT ENGINEER
LID & EW SECTION
Balussery Grama Panchayat